

# OSAGE UIC INSPECTION REPORT

(✓) Initial Inspection G.I. well  
 ( ) Follow-up Inspection

Permit No. \_\_\_\_\_  
 Inventory No. 4650  
 Date Inspection 5/1/86  
 Inspector AY

1. Company/Operator KWB Oil Prop. Mgmt. Inc.  
 2. Business Address 3300 First Nat Tower Tulsa, OK 74103  
 3. Individual Contacted NONE Title IC  
 4. Lease Name & Well No. AVANT #4 - (b) (9)  
 5. Legal Description (b) (9)  
 6. Well Information: Sub CR Injection zone 7377 - base USW

✓ GAS INJECTION WELL 1671 mcf  
 Authorized Injection: Pressure 25 psi Rate 45 bbl/d  
 7. Date of Last Inspection NONE Type ✓  
 8. Report of Conditions as of this date:

Well Status: Operating \_\_\_\_\_; through Tubing Yes \_\_\_\_\_ No \_\_\_\_\_  
 Not operating ✓; well equipped Yes \_\_\_\_\_ No ✓  
 Well plugged at surface \_\_\_\_\_ cannot determine  
 Required fittings on Tubing and Casing/Tubing Annulus Yes \_\_\_\_\_ No \_\_\_\_\_  
 Injection Pressure 0 psi; How Determined LINE DISCONNECTED  
 Injection Rate 0 BBL/D; How Determined \_\_\_\_\_  
 Corrective Actions Completed Yes \_\_\_\_\_ No \_\_\_\_\_ Not Determined \_\_\_\_\_  
 Records/Files Properly Maintained Yes \_\_\_\_\_ No \_\_\_\_\_ Not Determined \_\_\_\_\_  
 Samples Taken \_\_\_\_\_ Photographs Taken \_\_\_\_\_

Additional Comments and Observations: T.A., INACTIVE GAS  
INJECTION WELL. TUBING IN WELL IS BULL  
PLUGGED OFF. LINE FROM CSG/TBG. ANNULUS  
IS DISCONNECTED.

9. Corrective Action Required of Operator: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

10. The operator is to submit to the Oage UIC office, P.O Box 1495, Pawhuska, OK 74056 by \_\_\_\_\_ a report with adequate explanation and/or the corrective actions taken. If you desire to contact the field inspector by telephone, you may call (918) 287-4041.

Andrew A  
 Field Inspector

5/1/86  
 Date

Given to: \_\_\_\_\_

Date \_\_\_\_\_

Mail to: \_\_\_\_\_

Date \_\_\_\_\_

hC